

This staff gauge is located on 236<sup>th</sup> St SE, approximately 1/4 mile south of 34<sup>th</sup> Ave SE, (Lincoln Road) it is commonly referred to as the Wade Anderson Bridge. The gauge is located on the west side of the road just south of the bridge on a power pole. This location is on the Long Lake Creek just before it dumps into the McKenzie slough. This water usually pushes up from Long Lake. The reading on this gauge simply indicates a rise or fall of the creek level at that location.

<u>DATE/TIME</u>	<u>LEVEL</u>
3/19/19 3:00 PM	0.00
3/21/19 3:00 PM	0.50
3/25/19 3:00 PM	0.30
3/26/19 3:00 PM	0.40
3/27/19 3:00 PM	0.00
3/28/19 3:00 PM	0.40
3/29/19 3:00 PM	0.60
4/1/19 3:00 PM	0.00

